

V100C 固件说明

- 一、请使用神牛固件升级软件 G3 V1.1 打开该固件进行升级。 G3 V1.1 可在官网下载。
- 二、版本号查看方法：开机后，进入菜单界面，在最后面找到设备信息，可以看到软件版本号（如 1.00 版本：V1.00）。
- 三、版本说明：

版本	更新内容	日期
V1.05	优化使用体验。	25/1/9
V1.06	修复 M3、M6II、R7、R6II、R5 相机高速同步下 TTL 过曝的问题。	25/1/20
V1.07	1. 修复 M3、M6II、R3、R7、R8、R5/R5C、R5II、R6II、R10、R50、R100 相机高速同步下 TTL 过曝的问题。 2. 修复暗光环境下对焦可能触发 R 系列相机报 Err70 错误的问题。 3. 增加 TCM 开关和功率 0.3 档步进调节，可以在菜单中设置。	25/3/11
V1.08	修复部分相机使用 D、E 组不能开 TTL 的问题。（M3、M5 相机不支持）	25/6/17
V1.09	取消触屏长按解除锁定功能	25/7/14

注：详细规格请在官网（www.godox.com.cn）下载最新说明书。

V100C Firmware Release Note

- 1. Please update the firmware with Godox firmware update software G3 V1.1. G3 V1.1 can be downloaded on the official website.
- 2. How to check the version number:After the device is powered on, go to the menu page and find the device information at the very end. You can see the software version number (e.g. Version 1.00: V1.00).
- 3. Version Instructions:

Version	What's New	Date
V1.05	Optimize user experience.	25/1/9
V1.06	Fixed TTL overexposure in M3, M6II, R7, R6II, R5 cameras at high speed synchronization.	25/1/20

V1.07	1. Fixed TTL overexposure in M3, M6II, R3, R7, R8, R5/R5C, R5II, R6II, R10, R50, R100 cameras at high speed synchronization. 2. Fixed an issue where focusing in low light could trigger R Series cameras to report Err70 errors. 3. Add TCM switch and power 0.3 step adjustment, which can be set in the menu.	25/3/11
V1.08	Fixed the issue where some cameras cannot use the D and E groups to enable TTL function.(The M3 and M5 cameras are not supported)	25/6/17
V1.09	Disable the long-press touch screen unlock function.	25/7/14

Note: For more details, please download the newest instruction manual on the official website:
www.godox.com.