

V100C 固件说明

- 一、请使用神牛固件升级软件 G3 V1.1 打开该固件进行升级。 G3 V1.1 可在官网下载。
- 二、版本号查看方法：开机后，进入菜单界面，在最后面找到设备信息，可以看到软件版本号（如 1.00 版本：V1.00）。
- 三、版本说明：

版本	更新内容	日期
V1.05	优化使用体验。	25/1/9
V1.06	修复 M3、M6II、R7、R6II、R5 相机高速同步下 TTL 过曝的问题。	25/1/20
V1.07	1. 修复 M3、M6II、R3、R7、R8、R5/R5C、R5II、R6II、R10、R50、R100 相机高速同步下 TTL 过曝的问题。 2. 修复暗光环境下对焦可能触发 R 系列相机报 Err70 错误的问题。 3. 增加 TCM 开关和功率 0.3 档步进调节，可以在菜单中设置。	25/3/11
V1.08	修复部分相机使用 D、E 组不能开 TTL 的问题。（M3、M5 相机不支持）	25/6/17

注：详细规格请在官网（www.godox.com.cn）下载最新说明书。

V100C Firmware Release Note

1. Please update the firmware with Godox firmware update software G3 V1.1. G3 V1.1 can be downloaded on the official website.
2. How to check the version number: After the device is powered on, go to the menu page and find the device information at the very end. You can see the software version number (e.g. Version 1.00: V1.00).
3. Version Instructions:

Version	What's New	Date
V1.05	Optimize user experience.	25/1/9
V1.06	Fixed TTL overexposure in M3, M6II, R7, R6II, R5 cameras at high speed synchronization.	25/1/20
V1.07	1. Fixed TTL overexposure in M3, M6II, R3, R7, R8, R5/R5C, R5II, R6II, R10, R50, R100 cameras at high speed synchronization. 2. Fixed an issue where focusing in low light could trigger R Series cameras to report Err70 errors.	25/3/11

	3. Add TCM switch and power 0.3 step adjustment, which can be set in the menu.	
V1.08	Fixed the issue where some cameras cannot use the D and E groups to enable TTL function.(The M3 and M5 cameras are not supported)	25/6/17

Note: For more details, please download the newest instruction manual on the official website:
www.godox.com.