

X2T-S 发射器固件说明

- 一、请使用神牛固件升级软件 G3 打开该固件进行升级。G3 可在官网上下载。
- 二、本固件适用的发射器为在外壳喷码以 Z01 为结束的产品（喷码位置为 USB 口所在侧面或电池盖位置）或者 USB 口侧面贴纸上有 Z01 字样的产品。



- 三、版本号查看方法：发射器开机，按“MENU”按键进入菜单设置，在屏幕右上角显示固件版本号（如 1.1 版本：V1.1）。
- 四、版本说明：

版本	更新内容	日期
V1.4	1、配合手机 APP 的更新。	2022-06-30
V1.3	1、修复在与相机通信时，偶发的发射器无法正确接收通过蓝牙发送的设置值的问题。	2022-02-14
V1.2	1、修复设置为 APP 模式下，不发送修改过的值到接收端的问题。 2、恢复出厂设置时，重设蓝牙密码为初始值。 3、修复 Zoom 值设置的问题。	2020-07-20
V1.1	1、修复在 a6000、a6500 等相机最新固件下，开启防红眼闪光，漏闪的问题。	2019-08-13
V1.0	初始版本	

注：详细规格请在官网（www.godox.com.cn）下载最新说明书。

X2T-S Firmware Release Note

1. Please update the firmware with Godox firmware update software G3. G3 can be downloaded on the official website.
2. This version is compatible with X2T-S Trigger, which has a Z01 marking on the outer casing (near the USB port or on the battery cover) or has a sticker marking Z01 near the USB port.



3. How to check the version: turn on the X2T-C, and press the “MENU” button to enter menu

settings. The screen will display the firmware version (e.g. Version 1.1: V1.1) in the top right-hand corner.

4. Version Instructions:

Version	What's New	Date
V1.4	1. To match the update of Godox flash APP.	2022-06-30
V1.3	1. To solve the problem that occasionally X2T-S could not receive the correct settings sent over Bluetooth when communicating with the camera.	2022-02-14
V1.2	1. To solve the problem of not sending the modified value to the receiving end in APP mode. 2. When restoring the factory settings, the Bluetooth password is reset to the initial value (“000000”). 3. To solve the problem of the settings of Zoom value.	2020-07-20
V1.1	1. To solve the problem of turning on anti red eye flash and flash missing with the newest firmware of cameras like a6000 and a6500.	2019-08-13
V1.0	The original version	

Note: For more details, please download the newest instruction manual on

the official website: www.godox.com.